Customer Information Sheet

DRAWING No.: Z50-0X0 SHEET 3 OF 3 IF IN DOUBT - ASK (C) NOT TO SCALE THIRD ANGLE PROJECTION ALL DIMENSIONS IN mm



NOTES:

- I. TOOL Z50-020 TO BE USED WITH FEMALE M50-330XX42 CONNECTORS & TOOL Z50-030 TO BE USED WITH MALE M50-380XX42 CONNECTORS.
- 2. FOR OPERATING INSTRUCTIONS, SEE INSTRUCTION SHEET IS-43.
- 3. TERMINATION TOOL IS SUPPLIED WITH CLAMP, ASSEMBLED AND BOXED.
- 4. PRE-SET FEMALE TOOL (Z50-020) IS SET TO POSITION 27.
 PRE-SET MALE TOOL (Z50-030) IS SET TO POSITION 3. BOTH OF WHICH ARE DETERMINED BY COUNTING CLOCKWISE FROM MARKING ONE. THE TOOL IS CAPABLE OF TERMINATING BOTH MALE AND FEMALE. BUT THE DIAL SETTING WILL NEED TO BE ADJUSTED.

ORDER CODE:

Z50-0<u>X</u>0

TOOL:

FOR FEMALE = 2 FOR MALE = 3

CEE NOTE I

SEE NOTE I

MSP	2	12.06.17	2065
NAME	188.	DATE	C/NO

APPROVED: M.PERREN

CHECKED: M.PLESTED

DRAWN: M.PERREN

CUSTOMER REF.:

ASSEMBLY DRG:



www.harwin.com technical@harwin.com THIS DRAWING AND ANY
INFORMATION OR DESCRIPTIVE
MATTER SET OUT HEREON ARE
CONFIDENTIAL AND COPYRIGHT
PROPERTY OF THE HARWIN
GROUP AND MUST NOT BE
DISCLOSED, LOANED, COPIED
OR USED FOR MANUFACTURING,
TENDERING OR FOR ANY
OTHER PURPOSE WITHOUT

THEIR WRITTEN PERMISSION

TOLERANCES
X. = ±1mm

X.X = ±0.50mm X.XX = ±0.10mm X.XXX = ±0.01mm

ANGLES = ±5°

MATERIAL:

SEE ABOVE

FINISH: SEE ABOVE

S/AREA: mm²

TITLE:

M50 IDC TERMINATION

HAND TOOL

DRAWING NUMBER:

Z50-0X0

SHT 3 OF₃